Chains.

West on a true line bet. secs. 12 and 13.

Over gently rolling prairie.

20.02 Set an iron post, for 1/16 sec. cor. No. 1, bet. secs.
12 and 13, (E. 2) with brass cap stamped

1/16 S 12 in N. half No 1 S 13 in S. half

Dig pits 18x18x12 ins. E. and W. of cor. 3 ft. dist., and raise a mound of earth $3\frac{1}{2}$ ft. base, $1\frac{1}{2}$ ft. high, N. of cor.

40.04 The \$\frac{1}{4}\$ sec. cor. bet. secs. 12 and 13.

West of and alongside the stone, set an iron post, for witness cor. to the \$\frac{1}{4}\$ sec. cor., with brass cap stamped

\$ 12 in N. half S 13 in S. half and W C in addition

42.57 The C.C. of secs. 12 and 13 on reservation bdy.

West of and alongside the stone, set an iron post, for

witness cor. to the C.C., with brass cap stamped

C C in E. edge
T 21 N S 12 in NE. quadrant
R 23 E S 13 in SE. quadrant
P L I R in middle
and W C in addition

This cor. is 10.12 chs. S. 20° 34° E. of the 133½ M.P. From this cor., the old C.C. of secs. 12 and 13, which refers to surveys outside of the reservation, brs. N. 20° 34° W., 1.06 chs. dist.

Land, gently rolling prairie, - agricultural if irrigated. Soil, sandy loam, 1st rate.

From the 1/16 sec. cor. No. 12, bet. secs. 13 and 18 (S_2) on E. bdy. of Tp., I run

West on a true line through the S. half of sec. 13. Over gently rolling prairie.

20.00 Set an iron post for 1/16 sec. cor. No. 11, in center of the SE. quarter of sec. 13, with brass cap stamped 1/16 S 13 No 11.