

Chains

20.06 The 1/16 sec. cor. No. 6 bet. secs. 35 and 36, N $\frac{1}{2}$.

Land, level bottom.

Soil, sandy loam, 1st rate.

From the 1/16 sec. cor. No. 5 in the center of the NE $\frac{1}{4}$ of
sec. 35, I run

N. 89° 12' W. on a true line through the middle of the NE $\frac{1}{4}$
of sec. 35,

Over level bottom land.

3.00 Wire fence, brs. N. and S.

6.00 Irrigation canal, 10 lks. wide, course S. 45° E.

Leave level bottom; enter broken land, brs. NW. and SE.

23.67 Intersect Reservation bdy. at a point from which Sta. 4
brs. N. 54° 15' W., 8.43 chs. dist.

Set an iron post for 1/16 C. C. of sec. 35 on Reservation
bdy., with brass cap stamped

1/16 S 35 C C M I R in E.
1912 in S.

Raise mound of stone 3 ft. base, 2 ft. high, E. of cor.

Land, level and broken.

Soil, sandy loam, 1st rate; and stony, 3rd rate.

-- October 3, 1912.

NOTE:

The accompanying plat truly represents the results
of the survey of small Indian allotment tracts within the
section and subdivision lines hereinbefore described.

Guy P. Harrington,

United States Surveyor.