

List of Names

41

A list of the names of the individuals employed to assist in running, measuring or marking the lines and corners described in the foregoing field notes of the Sixth Standard North Ranges 31 and 32 East

of Mount Diablo base and meridian, showing the respective capacities in which they acted:

W. C. Watson	Compass man
J. B. Wilson	Chainman
W. J. Curren	Chainman
Thos. Perry	Axe man

We hereby certify that we assisted E. H. Lyle U.S. Deputy Surveyor in surveying the exterior boundaries of the Sixth Standard North Ranges 31 and 32 East