

# West Boundary T 27 N R 33 E

46

North between Sections 31  $\frac{3}{4}$  and 36  
Va 17° 33' E

- + 40.00 Set chained post in mound with  
pits as per instructions for 1/4 section  
main body of line about 8 chains  
N. bears N  $\frac{3}{4}$  W SSW
- W 42.00 Blight E  $\frac{3}{4}$  W
- to 46.00 Enter arm of line bears E  $\frac{3}{4}$  W N
- s 52.00 Leave arm of line, bears E  $\frac{3}{4}$  W
- 54.30 Enter arm of line, bears E, 5 chains  
59.90 Leave the same bears E  $\frac{3}{4}$  W
- 80.00 Set Chained post in mound with  
pits as per instructions, for corner  
to sections 35-30. 31  $\frac{3}{4}$  and 36.

Sand nearly level, soil poor  
and sandy. Some grasserwood  
and Sagerrod. Line about 13.00  
chains west of line.

5ch

E

5