

16/
Bet. Ranges 56, and 57. E. T. 33. N.

Mr. R. W.

From the Corner to Tps. 32, and 33, N. Ranges
56, and 57. E. Iran

North, On East Bdy. Sec. 36, bu. 12 1/2 E.

25.00 Enter grass land.

40.00 Set chanced 1/4 Sec. post in mound of earth with pits,
pr. instructions.

49.50 Cross Crk. 7 ebs wide, course N. by N.

55.00 Leave grass land.

80.00 Set chanced post in mound of earth with pits pr.
instructions for Cr. to Secs. 25, 30, 31, 36.

1st and 2nd, 2ate land, Grass, and mixed prairie.

North, On East Bdy. Sec. 25, bu. 17 1/2 E.

25.00 Enter grass land.

40.00 Set chanced 1/4 Sec. post in mound of earth with
pits pr. instructions.

54.00 Cross Crk. 3 ebs wide, course N. by N.

60.00 Leave grass, ascend, gradually.

80.00 Set chanced post in mound of earth with pits
for Cr. to Secs. 19, 24, 25, 30.

Mostly 1st 2ate level land. Fine grass,