

E 101

4000 set a Charred post in mound
 with fibs as per instructions for 1/4 sec cor
 8000 set a Charred post in mound
 with fibs as per instructions for
 Cor to rec 30-31-25-36
 Same level soil 2nd rate
 guano road ^{ma} Sagebrush

South Leg rec 31 ^{ma} 36
 La 17° 40' E

2360 A road to Balto Mountain mines
 runs NE & SW
 4000 set a Charred post in mound
 with fibs as per instructions for 1/4 sec cor
 8000 set a Charred post in mound with
 fibs as per instructions for Cor to
 Gunships 31 ^{ma} 32 N Ranges 441456
 Same level soil 2nd rate guano road.

February 26 1869