

T. 14 N R. 26 E Subdivision

In order to test the adjustment of my transit for the subdivision of this Township I commenced at the cor. to secs 34 & 35 on the S boundary and ran East on a blank line $N 17^{\circ} 10' E$.

at 39.91 ch $\frac{1}{4}$ cor is 7 lks S. and at 79.93 cor to secs. 35 and 36 is 4 links South. It is evident that the instrument is in adjustment as near as may be.

The East portion of the Township being mountainous and poor land I begin at the cor. to secs 34 & 35 on S boundary and run North between secs 34 & 35 -
 $N 17^{\circ} 10' E$