

85
110
E. boundary S 42 N. R 54 E. M. Drable Meridian
Edge bush

X North, between Sections 7^{and} 12
Var. 17° 45' East

40.00 Set a charred post in mound with pits
as per instructions for $\frac{1}{4}$ Sec Cor

80.00 Set a charred post in mound with pits as per
instructions for Cor. to Secs. 1-6-7^{and} 12
Land rolling - Soil 2nd rate
Edge bush

X North, between Sections 1^{and} 6
Var. 17° 45' East

40.00 Set a charred post in mound with pits as
per instructions for $\frac{1}{4}$ Sec. Cor. Whence a
Spring, bears N 17° E - 2^{ch} - 50th dial, flows N⁶

80.00 Set a charred post in mound with pits as per
instructions for Cor. to Townships 42^{and} 43
North, Ranges 54 and 55 East