

It is impossible to run the Eastern or Southern boundaries of T 35 N R 52 E. The lines passing over high rocky and precipitous mountains rendering it impossible to measure the lines and establish the corners thereon.

For description of Western and Northern boundaries see Field notes of Township 35 North Range 51 East, and of $7\frac{1}{2}$ Standard Parallel North.

General Description

The middle and Eastern portion of this Township is mountainous and unfit for Cultivation and destitute of mineral & timber. The Western portion is some of it level and suitable for cultivation.