

Third Standard Parallel North

start

West on the South boundary of Sec 32
 Var $16^{\circ}30'$ East

4000 set a Charred post in mound with
 pits as per instructions for $1/4$ Sec Cor

8000 set a Charred post in mound with
 pits as per instructions for Stand Cor
 to rec'd 31^{nd} 32^{nd}

Land level. Soil 2nd rate
 Greenwood ^{and} White Sage.

West on the South boundary of Sec 31
 Var $16^{\circ}30'$ East

4000 set a Charred post in mound with
 pits as per instructions for $1/4$ Sec Cor

8000 set a Charred post in mound with
 pits as per instructions for Stand Cor

To Tps 16 North Ranges 53^{rd} 54^{th} East
 having made allowance at each
 section corner for divergency