

10801

T. 30 N - R 41 E

North, between Sections 1st and 2

Var 17° 35' East

40.00 Set a charred post in mound with pit as
per instructions for $\frac{1}{4}$ Sec. Cor.80.80 Intersect the 6th Standard Parallel North
16 chs 80 lks W. of the Standard Corner to
Secs. 35th and 36 of T 31 N - R 41 E,
where I set a charred post in mound with pit
as per instructions for Closing Corner to
Secs. 1st and 2Land level - Soil 2nd rate

Greasewood

October 15th 1872North, between Sections 34th and 35

Var 17° 30' East

40.00 Set a charred post in mound with pit as
per instructions for $\frac{1}{4}$ Sec. Cor.50.00 Leave dry bed of Alkali Grass Bars N Eth and S W
Enter Greasewood