

E. boundary S. 38 N. T 56 E. M. D. M.

N.

- 10.00 Leave grassy bottom, bears E and W ascend
- 40.00 Set a charred post in mound with pits as per instructions for 1/4 Sec. Cor.
- 67.00 Summit of ridge, bears N. E. and S. W, descend  
"Copper" Cooppings, bear N. E. and S. W
- 77.00 Base of ridge, bears N. W, and S. E
- 80.00 Set a charred post in mound with pits as per instructions for corner to Sec. 1

1-6-7 and 12

Land lily - Soil 3<sup>rd</sup> rate

Sage brush some grass

Indications of Coal and of Copper

2.00

North, between Sections 1 and 6

40.00

Var. 17° 30' East

- 1.00 Base of ridge, bears N. W, and S. E. ascend 44.00
- 40.00 Set a post for temporary 1/4 Sec. Cor. 50.00
- 44.00 Summit of ridge, bears E and W, descend 55.00
- 80.00 Set a charred post in mound of stone 60.00