

W. D. W.

- near base of mountains
- 38.00 Leave meadow bears N<sup>W</sup> and S<sup>E</sup>  
ascend W slope of mountain base.
- 40.00 Set a charred post in mound with  
pits as per instructions for  $\frac{1}{4}$  Sec Cor.
- 80.00 Set a charred post in mound with  
pits as per instructions. for Corner to  
Sections 4, 5, 8 and 9.
- Land 1<sup>st</sup> 38 & 1<sup>st</sup> rate meadow  
Balance rolling Soil 2<sup>nd</sup> rate  
Bunch Grass and Sage Brush.
- Note Mountain Range 12 Chs East, bear N<sup>W</sup> and S.

North between Sections 4 and 5  
Town 14<sup>th</sup> 45' East

- 40.00 Set a charred post in mound with pits  
as per instructions for  $\frac{1}{4}$  Sec Cor.
- 50.00 Leave foot hills enter Rock Creek  
bottom bears N<sup>E</sup> and S<sup>W</sup>
- 80.28 Intersect the 7<sup>th</sup> Standard Parallel