

W. West Boundary of Tps 41 & 42 N 30 E. R. 29 & 30
 40.00 For $\frac{1}{4}$ Sec bor, set a charred post 48 in long
 squared $2 \times 2\frac{1}{2}$, 16 in in ground made
 mound 20 in high, dug pits $24 \times 12 \times 12$
 80.00 For bor to Sec 1, 6, 7 & 17, set a charred post
 48 in long squared 3×4 , 16 in in ground.
 made mound 20 in high, dug pits $24 \times 12 \times 12$
 Land level Soil 3rd rate
 Greasewood ✓

16 in
 ade
 2

North between Sections 1 and 6

Tar $170^\circ 45'$ East.

40.00 For $\frac{1}{4}$ Sec bor, set a charred post 43 in
 long, squared 2×2 , 14 in in ground, made
 mound 20 in high, dug pits $24 \times 12 \times 12$
 80.00 For bor to Tps 41 & 42 N Rgs 29 & 30 East,
 set a charred post 51 in long, squared 3×4
 16 in in ground, made mound 24 in high
 dug pits $24 \times 12 \times 12$.
 Land level, Soil 3rd rate Greasewood
 223. ✓
 1893