

Resurvey<sup>60</sup>

Exterior T40N R66E M.D.M.

8<sup>th</sup> Standard

Having examined the 8<sup>th</sup> standard parallel north through range 66 E. and finding some of the corners obliterated and others defaced I resurvey as follows:

Commencing on Sept. 17<sup>th</sup> at the cor to Twp. 41 N R. 65 & 66 E. I run.

S. 89° E. (which is the course through range 65 E.) on S boundary of sec 31.

Va 17° 30' E.

Ascending.

40.00 Willow post lying on ground. marks not legible. trace of mound and pits which I rebuild as follows.

Set a post 3 ft long 3 ins sq. with marked stone 12 ins in