

T38 NR 57 E M&M.

In the review and closure of the Northern part of section lines upon the new South Boundary of Tpk 39 NR 57 E established under the contract I find a great difference in the corners of the old survey, both on the Tpk line and in the subdivisions. I had already found and reported an error of over 10.00 chs in the old survey on the East Boundary of this Tpk — or West Boundary of T38 NR 58 E — and I find that the cor to sec 1-2-11 & 12 is the same distance out of the way as the Northern three and a half miles of the East boundary. Also that the old cor to sec