

S.B. 407

Retracing

Exteriors T. 35 N. R. 60 E. M.D.M.

Being unable to find the corner to Tps. 34 + 35 N. Rs. 59 + 60 E. I commence at the corner to Secs. 4, 5, 32 + 33 on the S. bdy. of T. 35 N. R. 60 E. which is a mound of stone around a rock 12 x 10 x 5 inches, about 6 inches in the ground, marked with 4 notches on E^{and} W^{od} W. edges. Thence I run S. 89° 53' W. on a blank line and find no trace of old corners.

I then return to the corner to Secs. 4, 5, 33 + 32, & run N. 89° 53' E. on a blank line on the S. boundary of the Township & find no old corners definitely established. I therefore run S. from the S.E. corner of the Tp. on my line and at the proper distances find the original 1/4 & Sec corners on the E. boundary of Secs. 25 + 36 T. 34 N. R. 60 E. which according to the information of a settler who has lived for over 20 years within a quarter of a mile of the N.E. corner of Sec. 30, are the original corners set in running the exteriors of this Township and which have never been disturbed.