

At 7 am. May 20th 1893 I find the
mag. bearing of the line established by me
last night to be N 16.5° W. the variation
is therefore 16° 55' E.

I begin at the cor. to Tps. 17 & 18 N. R. 60
& 61 East which is a post 3' dia marked
L. 18 N. L. 31 on NE

R 61 E. L. 6 .. SE.

L. 17 N. L. 1 .. SW.

R 30 E L. 36 .. NW. faces with 6 notches
on each edge with pits crosswise on
each line & mound of earth around
post. Thence I run

West on blank line on the South
boundary of Sec. 36. Var. 16° 55' E.
at 40 chs I find the 14 sec. cor. to
be 12 links north & at 80. 13 chs the
Sec. Cor. to be 44 lks north. I therefore
continue the true line West &
find that no portion of this South
boundary is in alignment or cor-
rect for distance but that the
cor. to Tps 17 & 18 N. R. 49 & 50 E is
N 89° 41' W of the starting cor. 0.1
miles 72 chs. 560 lks. As Tps 17 N.
R 60 E. has not been subdivided &
consequently no subdivision line have