

Resurvey.

Exterior T 30 N R 36 E. M D M

East Boundary

May 22nd 1895. Having examined the E. bay of Twp 30 N R 36 E. and finding most of the corners in a very dilapidated condition and some totally destroyed. I resurvey as follows. Commencing at a point.

3.06 chs. W of standard cor of Twp 31 N R 36 & 37 E. at which point I find traces of mound & pits but no post I set a rock 20 + 9 + 6 ins 10 ins in the ground for closing cor of Twp 30 N R 36 & 37 E. marked C.C on. South 6 grooves on S. & W. faces. and raised a mound of rocks 2 ft high 4 ft base covered with earth. S of corner.

Thence I run S bet sec. 10 & 6.

Descending. SW slope of mountain
Old road E & W