

2.

Resurvey 194

Exterior T29 & R. 36 E. M. Dm.

East Boundary

May. 30th Having examined the East boundary of this Township and finding most of the corners in a very dilapidated condition I resurvey as follows.

start

Commencing at the Cor of Twp 29 & 30 & R. 36 & 37 E. Iron
S bet secs. 1 & 6.

Over rolling lands.

10.00

Road S.W. & N.E

40.00

Old corner a post badly decayed
marks not legible lying on ground
face of mound pits I rebuilt as
follows set a post 3 ft long 3 ins sq.
24 ins in the ground for $\frac{1}{4}$ sec cor
marked $\frac{1}{4}$. On W face dug pits 18+18
+ 12 ins N.S. of post 4 ft. dist and
raised a mound of earth 1 1/2 ft high