

General Description

All of this township surveyed in this contract is mountainous, and is watered in the N.E. by Sasic & Middle Sasic creeks.

Dry Sasic creek runs through the east half of the township but does not flow continuously.

There is good grazing throughout with a little agricultural land in the bottoms provided that irrigation works be entered into.

There is no timber and but faint indications of mineral in the N.E. of the township.

In some cases stones could not be set to required depths but were fairly established as deep as possible.