

Subdivision of T40 N. R. 37 E.

Taking into consideration that the south boundary is erroneous in alignment, & as closures will necessarily be made on the north boundary on the Eighth Standard the Meeting of the East boundary need not be allowed for on this line, I therefore run a sectional correction line as follows.

At 1 ch 53 1/2 N. of the cor to secs 30 & 31 which I make the corner to these sections only by moving the ground to the East this being 50 chs plus the southing of the South boundary, I set a Granitic rock $15 \times 15 \times 8$ ins, 10 ins. in the ground for corner to secs 25 & 36 marked with 5 notches on N and 1 on S. Edges and raised a mound of stone West of cor.

June 11th At 8 a.m. S. on & set off $41^{\circ} 25' 8''$ on the latitude arc and $23^{\circ} 8'$ N on the decl. arc and determine a true meridian with the Solar.