

Special Report.

The country traversed by these lines lies on the very rocky & mountainous S.W. slope toward Mary's River. It is difficult in many places to set up an instrument on these slopes and an error was ~~evidently~~ made in alignment on this account or because of some undiscovered error in adjustment. The line bet. the first and second tier shows correct alignment and had the chainmen done good work the error in alignment would have been discovered at once. But they were probably