

*

162

The corner to Secs 4-5-8-9 -
~~the north boundary~~ had been
destroyed with its bearing tree
by exceptionally high water.
The original post was found
and replaced in its original
position. Pits were dug in each
section and a mound of earth
erected west of the corner.

The following are the only
necessary corrections to the
rolls of this township