

177. 21

Resurvey of the  
Subdivisions of T. 34 N. R. 38 E.

|       |  |
|-------|--|
| Chs.  | No. 2 E. lot sees. 5 and 6<br>This being true course found by<br>reticement.   |
|       | Over rolling land along<br>west slope  |
| 30.00 | Route course W.  |
| 36.50 | Route course NW.   |
| 40.00 | Find no trace of old $\frac{1}{4}$ sec. cor.<br>Set a granite stone $24 \times 24 \times 6$<br>ins. $18$ ins. in the ground for $\frac{1}{4}$<br>sec. cor marked $\frac{1}{4}$ on W. face<br>raise a mound of stone 2 ft.<br>base $1\frac{1}{2}$ ft. high W. of cor.<br>pile imperceptible |
| 45.00 | Route course W.  |
| 50.00 | Route course NW.   |
| 71.00 | Route course W.  |
| 74.00 | Road hors. NW. and SE.   |
| 80.50 | Cor of sees 5, 6, 31 and 32<br>which is a stake badly<br>decayed with markings<br>almost obliterated<br>I reestablish cor. in its<br>original position by setting a<br>granite stone $18 \times 10 \times 8$ ins.  |