

Retracement of E. Bdy. Twp. 34 N. R. 35 E.

May 9, 1905 At 5h. A.M. limit
I set off ^{1779' Non decl arc.} 40° 47' N. lat. arc and
determine a meridian with
Solar at the cor. of Twp. 33 and
34 N. Rps. 35 and 37 ^E as described
in original notes.

I retrace running N. 0° 1' E.
along the East Bdy of the
Twp. I find that the
entire line practically
agrees with my original
survey but at six miles
and forty links the
corner originally built
and marked for corner
common to both Twp.
is in error both in
construction and in
marking as the old
Twp. cor. as described in
Surveyor General's notes
and found by examiner
Hurlbert and found and
restored by me on May
8, 1905 ^{East} ~~East~~ ^{6.75}
~~seventy five~~ chains.

I destroy the markings

See page 1