

Resurvey.

7" Stand Bar. N. R33E

West on South Dec 35

Over small spur

3.75 Draw northeast

26.00 " southwest

40.00

32.50

Interested old D.C. - Stone too small ^{and}
 interested C.P. to see ~~548~~. Stone mtd as described
 mound partially destroyed

Set a quartzite $6 \times 8 \times 16$ ins mtd
 D.C. on N. face in mound stone
 $2\frac{1}{2}$ ft base $1\frac{1}{2}$ ft high.

Pits impracticable

Thence descending along broken ridge

80.00 Fall 17.00 Ch. S. of D.C. to less
 34035 wh is about stone $4 \times$
 18×20 ins mtd D.C. on N. 2 notches on
 East or West on mound stone

Pits impracticable

True Course ^{True dist}
 N $66^{\circ} 58' W$ 43.78

Land mountainous

Soil grassy rate.

Scattering sage brush

Memo.

Retrace by Standard two miles
 further west find it still trends
 toward the north.

Before running over Standard in
 N. 34 E, I subdivide in T 32 N. R 33 E.
 (See Book B, Extract No. 224)