

Re~~placement~~ of
Reservoir.

117

S bdy T 31 N R 33 E

On June 8th I go to cor. to Secs 34 & 35
on S bdy of T. 31 N R 33 E & with
the same inst. described in Notes of
Dyer Standard on June 1st 1901. I
after re-establishing cor. to 34 & 35
by setting ^a
x Limestone 6 x 12 x 18 ins mtd 2 mtd
on Cor. on West in mound of stone 3
ft base & 2 ft high. Pits empiric.
Draw Reservoir as follows:
East on S. Sec 35.

15.00 Spur new w.

19.00 Draw road new

24.00 Face 2.06 chs S. of a limestone 8 x 10 x 12
ins mtd 4 on N & set in mound of stone.
Fresher marks and repair mound

Continue ascent along SW slope True dist 24.08 Chs.

64.00 Face 5.50 S. of limestone 8 x 12 x 14 ins
marked for cor. to Secs 35, 36, 1 & 2 in
mound of stone. I fresher marks
and rebuild mound. True bearing N 85° 15' E
True dist 64.23 Chs.

Land mt. 64.13 chs.

Soil 3rd rate

Scattering cedars.