

Sixth Standard Par. R. 34 E. 141

S. bdy T. 31 N., R. 34 E.

I find cor. to Secs 33 & 34 on S. bdy of T. 31 N R 34 E and it is as described by Surveyor General but some what delapidated. Set stone 8 x 10 x 20 with same markings & rebuild mound around stone.

^{June 8th, 1901}
at 7 am, at this point I set off
22° 51' N on decl arc ~ 40° 30' N on lat arc
& run with two sets of chainman
using their average distances

Weston South bdy Sec. 33.

~~Near Magnetic direction 18° 30' E.~~

- | | |
|-------|--|
| 4.00 | Ascend on side cliff |
| 6.00 | Ridge ne sw |
| 27.00 | Steep ascent of rock cliff |
| 40.00 | On cliff set granite 8 x 12 x 14 ins
mld 4 O.C. on N. for 4 sec cor on S. sec
33 in mound stone 3 ft base 2 ft high
Pits impracticable |
| 41.50 | Ascend cliffs |
| 64.50 | Draw ee Ascend steep. |
| 84.00 | Set granite 6 x 8 x 12 ins mld 4 notches
on east and southwest. O.C. on north
for cor to Secs 32 & 33 in mound of stone
3 ft base 2 ft high.
Pits impracticable |
| | Land val - \$0.00 per ac. |
| | Soil 3rd & 4th rate |
| | Scattering Cedars. |