

Resurvey of E. Bdy of T. 32 N R. 51 E.

S. $0^{\circ} 16' E$ bet. secs. 31 and 36.

21.00

Intersect $\frac{1}{4}$ corner of sec. 31. Granite stone, $16'' \times 10'' \times 8''$ in mound of stones, as described. By surveyor-general. Marked stone out of position and mound scattered. I rebuild same.

Pits impracticable.

40.00

Set Granite stone, $16'' \times 10'' \times 6''$ in mound of stones $2\frac{1}{2}$ ft. base, $1\frac{1}{2}$ ft. high. marked $\frac{1}{4}$ on w face, for $\frac{1}{4}$ cor. of sec 36.

Pits impracticable

Along bench slopes S.

61.00

Intersect corner of Twp. 31 and 32 T. R. 52 E. Granite stone, $24'' \times 12'' \times 12''$ in mound of stones as described by Surveyor General. marked stone fallen and stones scattered. I rebuild cor.

Pits impracticable.

80.00

Set a Limestone, $18'' \times 12'' \times 8''$ in mound of stones, $2\frac{1}{2}$ ft.