

Resurvey of E. Bdy. of T. 82 N. R. 51 E.

From the cor. of 9 ps. 32 and
33 N., Rs. 51 and 52 E. 2 runs;
N 0° 6' W.

4.50

Ridge E.

18.00

Ridge E.

28.50

Ravine E.

30.50

Ravine bears E.

40.15

Intersect $\frac{1}{4}$ sec. cor. bet
secs. 31 and 36, which is
a decayed stake, fallen
and pits and mound
obliterated.

I restore point and set
Granite stone, $16 \times 8 \times 6 \frac{1}{2}$ ⁱⁿ
mound of stones, $2 \frac{1}{2}$ ft.
base, $1 \frac{1}{2}$ ft. high, marked
with $\frac{1}{4}$ on west face
for $\frac{1}{4}$ sec. cor. of secs.
31 and 36.

Pits impracticable.

57.00

Ridge bears N.E.

60.00

Ravine N.E.

72.00

Ridge N.E.

79.50

Ridge N.E.

80.39

Intersect cor of secs. 25,
30, 31, and 36, which is