

On making a retracement of the 4th Standard Parallel N. through Range 22 E. I find the corner to be on a due East and West line, and in a fair state of preservation, but in error as regards distance on the south boundaries of secs. 35 and 36.

Running East from the Standard cor. of secs. 34 and 35 as described by survey or General, I intersect the Standard $\frac{1}{4}$ sec. cor. on S. Bdy. of sec. 35 at 39.60 Chs. and the Standard cor. of secs. 35 and 36 at 78.98 Chs.

Continuing East on same line at 117.58 Chs. intersect the Standard $\frac{1}{4}$ sec. cor. on S. Bdy. sec. 36 at 156.98 Chs.

Intersect the Standard Township cor. of Tps. 21 N. Rgs. 22 and 23, East as previously described
May 5-1903