

Resurvey S. Bdy. T. 19 N., R. 24 E.

Chains but under size: mound dilapidated

446.10 No trace of cor.

475.10 Intersect Rd Tps. cor. a basalt stone 20X12X6 ins. in a mound of stone and marked with 6 notches on N., S., E., and W. edges.

Rebuild as follows:

Set the same stone firmly in a mound of stone, 3 ft. base, 2 ft. high and raise a mound of stone 2 ft. base, 1 1/2 ft. high S. of cor.

Pits impracticable

The cor. on this line being either in a poor condition or destroyed I deem it necessary to resurvey the entire S. bdy of T., 19 N., R., 24 E.

From the cor. of Tps. 18 and 19 N., Rqs. 23 and 24 E., I run; -