

14
2
Resurvey S. bdy T.42 N., R. 34E.

I retrace South bdy of Tp.42N.R.34 E. as follows;

June 7th. at cor Tps.41 and 42 N.Rs. 33 and 34 E., I run East, on a blank line.

I find the course of the line varies greatly and that a great many of the corners are out in alinement and in dist. and not as described by Sur.Gen'l. The corners, very few of which are standing, are of small willow stakes and too small for corners accordjng to requirements of the manual.

At 471.75 chs. I fall 1.50 lks N. of Tp. cor of Tps. 41 and 42 N. R. 34E. To verify this old cor I run N. and at 27.75 chs find cor to T's.41 & 42 N. R. 34 E.

Thence I run E. on N. bdy of Tp.41N. R.35 E., 40 chs found no trace of $\frac{1}{4}$ cor; 78.80 found what I thought to be old sec cor of Sec.31 and 32; 5 and 6. Finding the South bdy in such a condition and as the township south is not surveyed I decide to resurvey the S. boundary.

Beginning at cor to Tps.41 and 42 N. R.33 and 34 E. I resurvey as follows;

Where the old stake stood as described by the Surveyor-General I set a basalt stone 8x6x20 in, 13 in. in the ground for cor to T.41 and 42 N.R.33 and 34E. marked with 6 notches on each edge and dug pits 24x12x24 on each line N. E. and W. 4 ft. and S. of stone 8 ft. dist. and raised a mound of earth 5 $\frac{1}{2}$ ft. base and 3 ft. high S. of cor.

Thence I run

East on a true line bet. secs 31 & 6