

Resurvey of Subdivisions, J. 44th. R55 E.

I begin at cor. of secs. 4, 5, 32 and 33 and retrace sec. line N. bet. secs. 32 and 33 and at 40.00 chs. can find no traces of a $\frac{1}{4}$ sec. cor. At 80.00 chs. I can find no traces of the cor. to secs. 28, 29, 32 and 33.

Thence ³⁰⁰ E 40.00 chs. and can find no traces of $\frac{1}{4}$ sec. cor. bet. secs. 28 and 33.

From point for sec. cor. of secs. 28, 29, 32 and 33 I run N. and at 40.00 chs. can find no traces of $\frac{1}{4}$ sec. cor. bet. secs. 28 and 29. At 80.00 chs. I can find no traces of sec. cor. of secs. 20, 21, 28 and 29.

Thence W 40.16 chs. and I can find no traces of $\frac{1}{4}$ sec. cor. bet. secs. 20 and 29. At 80.33 chs. I can find no traces of sec. cor. of secs. 19, 20, 29 and 30.

From these retracements I find it necessary to resurvey the previously subdivided portion in order to complete the subdivision of this township.