

2.
10 Resurvey of Sixth Standard Parallel
North, Range 32 E.

chains
39.90

I find decayed post lying on the ground old marking obliterated.

80.00 No evidence of corner.

119.60 I find old $\frac{1}{4}$ post lying on the ground.

159.95 I find the Standard Corner to Township 31 N., Range 32 and 33 E. properly marked as described by the Surveyor General, but very dim, owing to decay of post.

I find the alignment and measurement of this line good for the total distance but the floating and decaying condition of corners demands a resurvey.

I destroy all traces of the old Standard Corner to T. 31 N., R. 32 and 33 E. and re-establish it at the same point as follows. Set a red wood post 3 ft. long 4 ins. sq. with marked stone 24 ins. in the ground for Standard Corner to T. 31 N. Rps. 32 + 33 E., marked S. C. T. 31 N. on N.