

4 484.

# Rebracement and Resurvey of

E. bdy. of T. 14 N., R. 26 E.

Chains R. 26 E. as has already been described on pages 83 and 84 in book entitled, "Survey of Township Exteriorst".

For reasons given in detail in book entitled "Survey of Township Exteriorst" on pages 78 to 85 inclusive we conclude it best to retrace and resurvey the W. bdy. of Tps. 14 and 15 N., R. 27 E. by restoring lost and obliterated corners as near as possible to their original places.

So we begin at old  $\frac{1}{4}$  sec. cor. on the E. side of secs. 24 T. 14 N. R. 26 E.

This is a granite stone  $12 \times 8 \times 3$  ins., as described by the U. S. Surveyor General for Nevada and we left imbedded 6 ins.