

Re Survey of E. bdy. of T 20 N R 43 E. T. D. M.

From the Cor. of Tps 19⁴/₂ 20 N. R. 43 E. which is a wooden post 4x2 ins. in mound of earth and stone marked 20 N on N. side and 44 E. on E. side. Having been set by County Surveyor in reestablishing old Cor. I destroy the Cor. and set at same point a sandstone 30x14x12 ins 23 ins in the ground for Cor. of Tps 19⁴/₂ 20 N. R. 43 E. marked 19 N on S.W. and 43 E on N.W. face, with 6 notches on N⁴/₂ N. edges. raise mound of stone 4 ft. base 2 ft. high N. of Cor.

Thence I run

North on blank line on E. bdy of Sec. 36.

40.00 find no trace of 1/4 Sec. Cor. set temp.

80.16 To pt. 8 Secs E. of Old Cor. of Secs. 25.30.31⁴/₂ 36 which is a mound of stone post destroyed I rebuild said Cor. at the same point referring to Secs. 29⁴/₂ 36 only as follows, set sandstone 19x10x4 ins. 13 ins. in the ground marked with 5 notches on N⁴/₂ 1 notch on S edge. raise mound of stone 4 ft. base 2 ft. high N. of Cor.

Thence I run

S 0° 03' E. on true line E. bdy. of Sec. 36. over rough stony ground sloping Westly

11.95 road to Amador Cañon at forks bear N.