

SUBDIVISIONS of  $S\frac{1}{2}$  T. 20 N., R. 23 E

chains

Dec. 5-1906.

Having resurveyed the E. and S. boundaries of this Twp. and finding both out of limits in both alignment and measurements, I deem it necessary to establish a Sectional guide meridian <sup>and</sup> Sectional correction line as per instructions in the manual.

At 8<sup>h</sup> 00<sup>m</sup> a.m., 1<sup>st</sup> mt. I set off.

$22^{\circ}16'S$  on decl. arc <sup>and</sup>  $39^{\circ}38'N$ .

on lat. arc and determine the meridian with Solar at the cor. of Secs. 35 <sup>and</sup> 36, on S. bdy, reestablished by me, and heretofore described.

Thence I run:

N. on a random line bet. Secs. 35 <sup>and</sup> 36.

40.75 Set temp.  $\frac{1}{4}$  sec. cor.

80.75 Set temp. point for cor of Secs. 25, 26, 35 <sup>and</sup> 36

At 9<sup>h</sup> 30<sup>m</sup> a.m., 2<sup>nd</sup> mt. I set off.  $22^{\circ}18'S$  on decl. arc <sup>and</sup>