

Resurvey W. Ldy. T21 N. R20 E.

- Chairs. N. $0^{\circ}23'E$. on true line bet. Secs.
1 and 6 over rolling land
- 4.15 Road, bears N. $15^{\circ}W$. and S. $15^{\circ}E$.
- 16.00 Road, (same) bears N. E . and S. W .
Enter Juniper timber
- 40.52 The $\frac{1}{4}$ sec. Cor. heretofore described
which I destroy and re-establish
as follows: Set a granite stone
 $20 \times 8 \times 6$ ins. 15 ins. in ground
for $\frac{1}{4}$ sec. Cor. Marked with
 $\frac{1}{4}$ on W. face
Pits impracticable
Juniper tree 8 ins. in dia.
bears S. $2^{\circ}30'E$. 1.11 chs. dist.
which I mark with
 $\frac{1}{4}$ S6 TBT.
- # Juniper 6 ins. dia bears
S. $75^{\circ}10'W$. 44 chs. dist.
mark with $\frac{1}{4}$ S1 TBT
- N. $0^{\circ}03'W$. from $\frac{1}{4}$ sec. Cor. ^{continue measurement}
- 44.00 Descend
- 51.00 Road, bears N. E . and S. W .
- 60.00 Dry wash, course S. E .
- 63.50 Top of low ridge, desc.
- 80.70 The Cor. of Tps. 21 and 22 N., Rgs.
19 and 20 E. heretofore described
which I destroy and re-establish