

2052

Resurvey of N. bdy. T²¹N., R²⁰E

Chas no trace of mound or pits.

277.33 I find $\frac{1}{4}$ sec. cor. a Stake
2 $\frac{1}{2}$ ft. long 2 $\frac{1}{2}$ ins sq. 3.04 chs. N.
of line

317.38 I find cor. of Secs. 5, 6, 31 and 32
a Stake 2 $\frac{1}{2}$ ft. long 3 ins sq.
marks nearly obliterated
2.812 chs. N. of line, No trace
of pits or mound

357.38 I find no trace of $\frac{1}{4}$ sec. cor.
Set temp $\frac{1}{4}$ sec. cor.

399.70 Intersect the W. bdy. of Tp.
^{3.85} 3.85 chs. N. of the Cor. of
Tps. 21 and 22 N., R⁹S. 19 and 20
E. heretofore described

April 8-1906

From the foregoing I conclude
that the random line
mentioned in approved
notes was never corrected
to true line as stated and
that instead of intersecting
the W. bdy 3 $\frac{1}{2}$ chs N of the
corner that he really did
so at a point 6.62 chs. N of
Same and furthermore
his chainman made a