

Resurvey of S. 1/4 of T24 N. R. 33 E.

Tuesday May 15, at the cor. of
Tps. 2 and 24 N R. 32 and 33 E
previously reestablished and described
by me, I observe a flag at the
cor. of secs. 25, 30, 31, and 36.
one mile north, from which I
lay off 90° to the East and run
east on a blum line along the S.
bdy of T24 N R 33 E, searching
for corners at 40 and 80 chain
intervals, and at 78.10 chs, the
old corner of secs. 5, 6, 35 and 36
which is a post badly decayed no
marks legible except the notation
on the edges, mound and pits
nearly obliterated bears N. 3 lks
distant. I continue my line
east searching at 40 and 80 chain
points, and at 438.01 chs, the $\frac{1}{4}$
sec cor. bet. secs 1 and 36, a post
with marks barely legible lying
on a low mound of earth, pits
practically obliterated bears N.
73 lks dist. I continue my
line east and at 478.01 chs
search diligently within a