

CORRECTIVE NOTES OF

RETRACEMENT OF THE WEST BOUNDARY OF T.2 S., R.53 E.

Note:

I destroy all cors.set on the west boundary of T. 1 S., R.53 E., as set on original survey.

September 23: At 7h.53m., a.m., l.m.t., I set off  $37^{\circ}41'N.$  on lat.arc,  $0^{\circ}03'N.$  on decl.arc, and determine a meridian with the solar at a point 40.00 chs.south of the  $\frac{1}{4}$  sec. cor.bet.secs.31 and 36, on W.bdy.of T.2 S., R.53 E.

Thence I run south, along the west boundary of T.3 S., R.53 E., and can find no trace of any cor., I continue south along the west boundary of T.4 S., R.53 E. and after diligent search can find no trace of any cor. and the topography does not agree in any instance with the topography as furnished by the surveyor general.

I also look for evidences of cors.on the N.and S.bdys. of T.3 S., R.53 E., on the First Stan.Par.South and in the Subdivisions of T.4 S., R.53 E., but in no instance can I find cors.or evidences of cors.

Note:

On this corrective survey all old cors.of the original survey have been destroyed, where they are different from the corrective survey.

All cors.of the lines of Rs.51 $\frac{1}{2}$  and 52 E., not included in the corrective notes have been destroyed.

*Frank T. Roberts*  
U.S. Deputy Surveyor