

CORRECTIVE SURVEY OF THE RANGE LINE THRU TOWNSHIP 4 SOUTH, BET. RS. 47 AND 48 E.

CHAINS

This survey was made in compliance to Hon. Commissioner's letter, Completion of Contract No. 250, dated May 1, 1912, wherein I was required to re-establish in good condition the corner monuments along the range line between ranges 47 and 48 E., Tps. 3 and 4 S.

May 21, 1912: I begin at the standard corner of Tps. 4 S., Rs. 47 and 48 E., which is described in the original field notes and run for re-establishment and overhauling of corners as follows:

North, bet. secs. 31 and 36.

40.00 The 1/4 sec. cor. which was found in good condition as described in the original field notes.

80.00 I remark 1 notch on S. edge and 5 notches on N. edge, of the stone described in the original field notes and rebuild the mound of stone, 2 ft. base, 1 1/2 ft. high, W. of cor. Pits impracticable.

There is no change of topography on this line.

North, bet. secs. 25 and 30.

40.00 The original corner set at this point was well marked and well set, I rebuilt the mound of stone, 2 ft. base, 1 1/2 ft. high, W. of cor. Pits impracticable.

80.00 I remark 2 notches on S. and 4 notches on N. edges, on the stone described in the original field notes, and rebuild the mound of stone, 2 ft. base, 1 1/2 ft. high, W. of cor. Pits impracticable.

There is no change of topography on this line.

North, bet. secs. 19 and 24.

40.00 I remark 1/2 on W. face of original stone described in the original field notes and dig pits, 18x18x12 ins., N. and S. of stone, 3 ft. dist., and raise a mound of earth, 3 1/2 ft. base 1 1/2 ft. high, W. of cor.

80.00 I remark 3 notches on N. and S. edges, of the stone

See Book B p. 13 (45)

See Book "B" p. 14 (46)