

CORRECTIVE NOTES OF THE SOUTH BOUNDARY OF T.9 S., R.43 E.

CHAINS

original field notes.

West, bet. secs. 4 and 33.

40.00 Intersect the  $\frac{1}{4}$  sec. cor., described in original field notes.

80.00 Intersect the cor. of secs. 4-5-32 and 33, described in original field notes.

For orig. Field Notes see Bk "E" p 28 [p 276]

West, bet. secs. 5 and 32.

40.00 Intersect the  $\frac{1}{4}$  sec. cor., described in original field notes.

80.00 Intersect the cor. of secs. 5-6-31 and 32, described in original field notes.

For orig. Field Notes see Bk "E" p 27 [p 275]

West, bet. secs. 6 and 31.

40.00 Intersect the  $\frac{1}{4}$  sec. cor., described in the original field notes.

89.95 Intersect the closing cor. of Tps. 9 and 10 S., R. 43 E., on the Reese River Guide Meridian, described in original field notes.

For orig. Field Notes see Bk "E" p 26 [p 274]

February 19, 1908

SOUTH BOUNDARY OF T.9 S., R.44 E.

The  $\frac{1}{4}$  sec. cor. on the S. bdy. of T.9 S., R.44 E., bet. secs. 6 and 31, which was reported missing by the examiner of surveys, was found by me to be in place, plainly marked with mound of stone delapidated.

I rebuilt the mound of stone, 2 ft. base,  $1\frac{1}{2}$  ft. high, N. of cor.

Pits impracticable.

*Melvin D. Hint*

U. S. Deputy Surveyor