

Resurvey of Subdivisions of T. 17 N. R. 44 E.

Chains N. 89° 36' W. bet. secs. 2 and 11.
2.43 Old road, bears S.E. and N.W.
31.40 Ravine, course S.E.
36.80 Old road, bears S.E. and N.W.
40.01 Found old pits and mound of original $\frac{1}{4}$ sec. cor., which I destroy and reestablish at the same point. Set a quartz rock 18x13x6 ins. 12 ins. in the ground for $\frac{1}{4}$ sec. cor. to secs. 2 and 11, marked $\frac{1}{4}$ on N. face and raise a mound of stone 2 ft base $1\frac{1}{2}$ ft. high N. of cor.
Pits impracticable.
Land, mountainous.
Soil, stony, second rate.
Timber, sagebrush.
Mountainous land, covered with dense brush, very difficult to survey, 40.01. *chs.*

March, 31 st. 1909.

GENERAL DESCRIPTION.

The western part of this township is very rough and mountainous in character. The eastern part is fairly smooth and level. It slopes to the east. The western part appears to be mineralized, although there are no producing mines thereon.

It is all good grazing land. There are settlements in sections 9, 16, and 17.

William T. Seavey

U.S. Deputy Surveyor.