

Boundaries of northern portion of T 32 N, R 40 E.

25

57

Boundaries of northeastern portion of T 32 N, R 40 E.

Latitudes, departures and closing errors.

Lines designated.	True bearing.	Dis- tance.	Latitudes.		Departures.	
			N	S	E	W
W. of sec. 2	S 0° 2' E	80.29		80.29	.05	
N. of sec. 10 { E 1/2	West	40.00				40.00
	N 89° 27' W	39.90	38			39.90
W. of sec. 10	S 0° 4' E	80.00		80.00	.09	
W. of sec. 15	S	80.12		80.12		
S. of sec. 15	E	80.00			80.00	
W. of sec. 23	S 0° 2' E	80.00		80.00	.05	
S. of sec. 23 and 24	E	160.00			160.00	
E. of sec. 24	N	78.90	78.90			
E. of sec. 13	N 0° 6' E	80.80	80.80		.14	
E. of sec. 12	N 0° 15' E	79.80	79.80		.35	
E. of sec. 1	N 0° 20' E	80.22	80.22		.47	
N. of sec. 1 and 2.	N 89° 46' W	161.06	.67			161.06
Convergency Totals			320.77	320.41	241.15	241.16
			320.41			241.15
Error in lat.			.36		Error in dep.	.01

General Description.

Nearly all of the land embraced in this survey is mountainous and unfit for cultivation. The mountains are formed of lime, granite, and eruptive rocks, with some indications of mineralization.

They are covered in places with a scattering growth of juniper trees. In secs. 10, 11 and 12 there is some rolling ground where the soil is good and which would be very productive if it could be irrigated but there is no water available for this purpose. I do not think dry farming would be successful here. All the land surveyed is covered with a good growth of sage-bush, but there is not much grass.