

Chains.

W. on a true line bet. secs. 7 and 18.
Over level land.

8.00 Wash, course N.W.
40.00 Set an iron post 3 ft. long, 1 in.
diam. 24 ins. in the ground for
 $\frac{1}{4}$ sec. cor. with brass cap m'kd.

$$\begin{array}{r} 57 \\ \frac{1}{4} \\ \hline 518 \\ 1911 \end{array}$$

dig pits 18x18x12 ins. E. and W. of post
3 ft. dist. and raise a mound of earth
3 $\frac{1}{2}$ ft. base, 1 $\frac{1}{2}$ ft. high N. of cor.

52.00 Wash, course N.W.
75.30 Intersect the W. bdy. of the tp. at
S0.2.E, 2.60 chs. from the cor. of secs.
12 and 13.

Set an iron post 3 ft. long, 2 ins. diam.
24 ins. in the ground. for closing
corner of secs. 7 and 18, with brass cap
m'kd.

$$\begin{array}{c} T32N \\ R41E \quad R42E \\ \hline 512 \quad 57 \\ \hline cc \quad \hline 513 \quad 518 \\ \hline 1911 \end{array}$$

dig pits 24x18x12 ins. crosswise on
each line, N. and S. 3 ft. and E. of
post 7 ft. dist.; and raise a mound
of earth 4 ft. base, 2 ft. high E. of cor.
Land level.

Soil, good loam. 1st. rate, fine
land, rich, fertile soil, good growth
sagebrush, little grass, no timber,
slopes N.W.

May 15, 1911.

May 16, 1911
N 0.10.W bet. secs. 7 and 8
Over level land.