

Re-survey of 1st. Standard Parallel North
through R 59 E

Chains.

- 47.00 Mountain spur, slopes S. E.
50.50 Small ravine, course S. E.
52.20 Low mountain spur, slopes S. E.
55.00 Ravine, course S. E.
80.70 Limestone hill, bears N. and S.
82.72 On N. W. slope

The standard corner of T⁶ N, R⁵⁸ and S⁹ E

I destroy all traces of this corner and the mound of earth and stone in which it was set, and re-establish it at the same point as follows.

Set a limestone $24 \times 15 \times 12$ ins., 16 ins. in the ground for standard corner of T⁶ N, R⁵⁸ and S⁹ E, marked S. E. on N. with 6 grooves on the N., E., and W. faces, and raise a mound of stone 2 ft. base, $1\frac{1}{2}$ ft. high N. of cor.

I do not disturb the old bearing trees. Land, rolling, volcanic and limestone mountains.

Soil, poor and rocky, of little depth, 4th rate. Unfit for cultivation. Good growth sagebrush, little grass, scattering juniper, scrub pine and mahogany trees.

General southerly slope.

October 22, 1913

Subdivision of T⁶ N R⁵⁹ E

Oct. 23, 1913

At the standard cor. of sec. 35 and 36, re-established by me Oct. 22, 1913

at 8 h., a.m., l.m.t., I set off $38^{\circ} 19' N$ on the lat. arc, $11' 17'' S.$ on the decl. arc and determine a meridian with the solar shadow I run

N $0^{\circ} 7' W$ bet sec. 35 and 36

Over level land.