

Boundaries of T. 28 N. R. 31 E.
 Latitudes, Departures and closing errors.

Line designated	True bearing	Distance	Latitudes			
			N.	S.	E	W
W. bdy. T 28 N. R 31 E	North	397.85	397.85			
N. Bdy " " "	East	405.85		405.85		
E. bdy. Sec. 2	S 1° 00' W	80.22		80.22		1.40
S. bdy Sec. 2	S 89°-55' W	80.26		.11		80.26
E. bdy Sec. 10	South	80.00		80.00		
S. bdy Sec 10	N 88°-05' W	80.12	2.68			80.12
E. bdy Sec 16	S. 0°-2' W	80.06		80.06		.05
S. bdy Sec. 16	S. 89°-57' W	80.20		.07		80.20
E. bdy Sec. 20	S. 0°-6' E	79.94		79.94	0.14	
S. bdy Sec. 20	S. 89°-47' W	80.04		0.30		80.04
E. bdy Sec 30	S. 1°-18' W	80.15		80.15		1.81
S. bdy Sec. 30	N 89°-33' W	81.92	.63			81.92
Convergency					.25	
			401.16	400.85	406.24	405.80
			400.85	error in	405.80	
Error in Lat.			.31	Departures	.44	

General Description.

The land surveyed within this township was nearly all rough, ^{rolling and} mountainous, the land in sec. 6 being extremely rough and mountainous. The soil is rocky and can nearly all be classed as third rate, unfit for agriculture.

There are indications of mineral, principally gold along the northern tier of sections, especially in sec. 5 where considerable prospect and development work has been done.

A spring of good water was found in the western part of sec. 5, which supplied about 6 barrels of water per day. A shaft containing good water is located in the northeast cor. of sec. 9. There are no settlers within the township.